

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Assistant Engineer)

(Re: G.O. Ms. 20/70/PWD Dt. 23-01-1970)

1. Name of Officer : **SINDU.V.J, ASSISTANT ENGINEER**
2. Name of School : **CHINMAYA VIDYALAYA, VELLAPPALLY,**
NARUVAMOODU
3. Location with Name of Education Dist./Sub Dist. : **Neyyattinkara/Balaramapuram**
4. Classification of Building as specified in column 4
of the application for fitness certificate and size : **1X50.70X9.60m – GF**
1X50.70X9.60m – FF RCC Building
1X50.70X9.60m – SF
1X6.00X6.60 mPorch & Staffroom
1x20.80x13.10m- RCC
1x7.00x3.50m-RCC
1x28.20x6.60 sheet roof
5. Nature of Defects, if any : **2026-2027 Academic Year**
 - a) Foundation & Basement :
 - b) Superstructure :
 - c) Door & Windows : **No major defects were found**
 - d) Wood work Wrought & Put up : **during inspection**
 - e) Roof :
 - f) Flooring :
 - g) Miscellaneous (Cracks etc) :
6. Any major defects noticed which will render
the building unsafe in any manner : **NIL**
7. Whether maintenance works have been done properly : **YES**
8. Whether the structure is sound or not for : **YES, sound enough under normal weather condition**


- Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc
2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate

CERTIFICATE

Certified that the school building was inspected by me on **29/05/2026** and found to be fit to conduct classes, for the **2026-2027** academic year under normal weather conditions for the reasons stated above, except one lean to roof building mentioned above. The safety of electrical wiring and fire extinguishers are not verified.


Place: Pallichal

Seal

Signature: 

Date :

Designation



**ASSISTANT ENGINEER
LSGD SECTION
PALLICHAL GRAMA PANCHAYAT**